Smart Solutions Bristol Ltd
117 Wedmore Vale, Bristol, BS3 5EW
smartsolutionsltd.com · Company 16203244

Certificate of Fire Damper Testing

What was checked: functional (drop) test and visible condition, following BESA DW145 Appendix C. Installation was not checked against the maker's instructions.

FULL REGISTER

SITE TESTED
Calderbrook House
22 Calder Row, Bristol, BS2 0ZJ

DROP-TESTED	OUTCOME	NEXT TEST DUE
6 of 6	**SATISFACTORY**	10 June 2027

Please pass this report to whoever carries out the building's fire risk assessment.

DATE TEST UNDERTAKEN
10 June 2026

REPORT REFERENCE
1003

SYSTEM
Riser A

SMART CERTIFICATE REFERENCE
K5N2-TWF8

DUE NOW - REPAIR AND RETEST
None

REMEDIAL ADVISED
None

Every damper that could be reached was inspected and, where its type allows, drop-tested by a competent person. The result for each damper, including any that would not close or could not be reset, is in Fire Damper Test Report 1003, which forms part of this pack. Faulty dampers should be repaired or replaced immediately (BESA DW145). Article 17 of the Regulatory Reform (Fire Safety) Order 2005 requires the responsible person to ensure that facilities, equipment and devices provided for fire safety, such as fire dampers, are subject to a suitable system of maintenance and are maintained in an efficient state, in efficient working order and in good repair. To confirm the authenticity of this document, quote the certificate reference above to Smart Solutions Bristol Ltd.

CARRIED OUT BY
Tom Reeve
Tom Reeve

AUTHORISED BY
Sam Ellis

SMART SOLUTIONS BRISTOL LTD · ISSUED BY
K5N2-TWF8
10 June 2026