Smart Solutions Bristol Ltd

117 Wedmore Vale, Bristol, BS3 5EW
smartsolutionsltd.com · Company 16203244

Certificate of Ventilation System Cleaning

Ventilation system cleaned using the TR19® Air method

FULL CLEAN

SITE CLEANED
Cedar Row Clinic

12 Cedar Row, Bristol, BS6 0ZZ

HIGHEST POST-CLEAN DUST (LAB)	RESULT	NEXT INSPECTION DUE
0.05 g/m²	**PASS**	10 November 2027
limit 0.3 g/m² · high · supply		

DATE CLEAN UNDERTAKEN
10 November 2026

PVR REFERENCE
1018

SYSTEM
AHU-1 treatment wing supply

SMART CERTIFICATE REFERENCE
UBYB-UN2P

INSPECTION REPORT
None recorded

VHR MEMBERSHIP (AIR)
Not recorded
This clean: certificate not recorded

CLEANLINESS CLASS
High · supply · the whole system is next inspected on 10 November 2027

Cleaned and verified by an air hygiene technician. Post-clean dust was measured by vacuum test at every test point and weighed by Sample Analytical Lab, whose certificate is attached; every point must be under the limit for its class. This certificate must be read with Post Clean Verification Report 1018, which forms part of this pack. To confirm the authenticity of this document, quote the certificate reference above to Smart Solutions Bristol Ltd.

CARRIED OUT BY
Tom Reeve
Tom Reeve

AUTHORISED BY
Sam Ellis

SMART SOLUTIONS BRISTOL LTD · ISSUED BY
UBYB-UN2P
10 November 2026

Cedar Row Clinic
10 November 2026, UBYB-UN2P
DEMONSTRATION - NOT A COMPLIANCE RECORD

Your trade body's badge here

Smart Solutions Bristol Ltd